



Larmos Autoservices

Technician: Andreas Larmou

Date: 29/10/2025

Customer Name: Car Addicts Cyprus

Yr/Make/Model: 2008 Alfa Romeo Spider 2.2 JTS

VIN: ZAR93900005024685

Mileage: 85500 kms

ENGINE & COOLING SYSTEM

Oil & coolant levels and condition

☒	☐	☐
☐	☒	☐
☐	☒	☐
☒	☐	☐
☒	☐	☐

Engine noise / vibration / **leaks**

Cooling system hoses / radiator / fan

Belts & pulleys condition

ECU codes / exhaust smoke / idle quality

Comments: Coolant level at minimum

Power steering tank leak

Engine oil level ok

ELECTRICAL SYSTEM

Battery voltage / terminals / charging

☐	☒	☐
☒	☐	☐
☐	☒	☐

Starter motor / alternator function

Lights & indicators / dashboard warnings

Comments: Front bulbs

Rear right tail light condensation

Battery voltage at no load: 12V - Battery voltage under load: 10.8V

AIR CONDITIONING & HVAC

Compressor / airflow / temperature

☒	☐	☐
☒	☐	☐

Heater function

Comments: _____

DIAGNOSTIC SCAN

Fault codes retrieved

☐	☒	☐
☐	☒	☐

Systems check

Comments: 1. P0571 - The ECU isn't receiving a consistent signal from the brake

pedal switch. 2. P1161 - The ECU detects a mismatch between expected and

actual throttle/fuel control parameters. 3. P0159 - The post-catalytic oxygen

sensor (downstream) is responding slower than expected.

EXHAUST SYSTEM

Visual condition / corrosion

☐	☒	☐
☒	☐	☐

Mouting brackets secure

Comments: Surface rust on the exhaust system - no holes detected

SUSPENSION & STEERING

Front & rear suspension bushes

☐	☒	☐
--------------------------	-------------------------------------	--------------------------

Ball joints / tie rods / rack condition

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Shock absorbers / struts / bushes

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Comments: Front suspension arm - rear bushes need replacement soon

BRAKING SYSTEM

Brake pad / disc condition

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Brake hoses / lines / leaks

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Brake fluid level & color

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Handbrake / ABS operation

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Comments: _____

TRANSMISSION, CLUTCH & DIFFERENTIAL

Gearshift operation / smoothness

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Clutch pedal feel & bite point

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Transmission fluid level / leaks

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Differential operation / noises

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Comments: _____

WHEELS & TYRES

Tyre tread depth / brand matching

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Wear pattern

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Wheel condition / cracks

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

Comments: Tyre Condition - Very Good

Tyre Brand and age: Davanti DX640 / Week 22 of 2021

Wheels: Small marks - No cracks

Mechanic's Signature: _____



Date: 29/10/2025

Disclaimer:

This Vehicle Inspection Report was produced for and paid for by Car Addicts Cyprus. The inspection reflects the vehicle's condition only at the time and date it was examined. All observations and findings are based on a visual and functional inspection carried out without dismantling any components, unless otherwise stated.

While every effort has been made to ensure accuracy, Car Addicts Cyprus and the inspecting technician assume no responsibility or liability for any mechanical, electrical, or cosmetic issues that may arise after the date of inspection. This report does not constitute a warranty, guarantee, or valuation of the vehicle, and it should not be relied upon as the sole basis for a purchase decision.

Δήλωση Αποποίησης Ευθύνης:

Η παρούσα Έκθεση Ελέγχου Οχήματος εκπονήθηκε για λογαριασμό και με δαπάνη της Car Addicts Cyprus. Ο έλεγχος αντικατοπτρίζει την κατάσταση του οχήματος μόνο κατά την ημερομηνία και ώρα της επιθεώρησης. Όλες οι παρατηρήσεις και τα ευρήματα βασίζονται σε οπτικό και λειτουργικό έλεγχο, χωρίς αποσυναρμολόγηση εξαρτημάτων, εκτός εάν αναφέρεται διαφορετικά.

Παρά τη μέγιστη δυνατή προσοχή για την ακρίβεια των πληροφοριών, η Car Addicts Cyprus και ο τεχνικός που διενήργησε τον έλεγχο δεν φέρουν καμία ευθύνη ή υποχρέωση για μηχανικά, ηλεκτρικά ή αισθητικά προβλήματα που ενδέχεται να προκύψουν μετά την ημερομηνία του ελέγχου. Η παρούσα έκθεση δεν αποτελεί εγγύηση, διαβεβαίωση ή αποτίμηση της αξίας του οχήματος και δεν πρέπει να χρησιμοποιείται ως ο μοναδικός παράγοντας για λήψη απόφασης αγοράς.