



Larmos Autoservices

Technician: Andreas Larmou

Date: 22/01/2026

Customer Name: Car Addicts Cyprus

Yr/Make/Model: 2021 Toyota Yaris GR 1.5l

VIN: MXPA12-0002507 (Chassis Number)

Mileage: 31250kms

ENGINE & COOLING SYSTEM

Oil & coolant levels and condition	☒	☐	☐
Engine noise / vibration / leaks	☒	☐	☐
Cooling system hoses / radiator / fan	☒	☐	☐
Belts & pulleys condition	☒	☐	☐
ECU codes / exhaust smoke / idle quality	☒	☐	☐

Comments: No Engine/Transmission ECU Codes

ELECTRICAL SYSTEM

Battery voltage / terminals / charging	☒	☐	☐
Starter motor / alternator function	☒	☐	☐
Lights & indicators / dashboard warnings	☒	☐	☐

Comments: Ok

AIR CONDITIONING & HVAC

Compressor / airflow / temperature	☒	☐	☐
Heater function	☒	☐	☐

Comments: Ok

DIAGNOSTIC SCAN

Fault codes retrieved	☐	☒	☐
Systems check	☐	☒	☐

Comments: Diagnostic Report Attached

EXHAUST SYSTEM

Visual condition / corrosion	☒	☐	☐
Mouting brackets secure	☒	☐	☐

Comments: Ok

SUSPENSION & STEERING

Front & rear suspension bushes	✓		
Ball joints / tie rods / rack condition	✓		
Shock absorbers / struts / bushes	✓		

Comments: Ok

BRAKING SYSTEM

Brake pad / disc condition		✓	
Brake hoses / lines / leaks	✓		
Brake fluid level & color	✓		
Handbrake / ABS operation	✓		

Comments: Brake Pads OK!

Brake Discs - 30% Corrosion - Not affecting safety - just visual

TRANSMISSION, CLUTCH & DIFFERENTIAL

Gearshift operation / smoothness	✓		
Clutch pedal feel & bite point	✓		
Transmission fluid level / leaks	✓		
Differential operation / noises	✓		

Comments: Ok

WHEELS & TYRES

Tyre tread depth / brand matching	✓		
Wear pattern	✓		
Wheel condition / cracks	✓		

Comments: Zealion ZMax 225/40/18

Ok

Mechanic's Signature: 

Date: _____

Disclaimer:

This Vehicle Inspection Report was produced for and paid for by Car Addicts Cyprus. The inspection reflects the vehicle's condition only at the time and date it was examined. All observations and findings are based on a visual and functional inspection carried out without dismantling any components, unless otherwise stated. While every effort has been made to ensure accuracy, Car Addicts Cyprus and the inspecting technician assume no responsibility or liability for any mechanical, electrical, or cosmetic issues that may arise after the date of inspection. This report does not constitute a warranty, guarantee, or valuation of the vehicle, and it should not be relied upon as the sole basis for a purchase decision.

Δήλωση Αποποίησης Ευθύνης:

Η παρούσα Έκθεση Ελέγχου Οχήματος εκπονήθηκε για λογαριασμό και με δαπάνη της Car Addicts Cyprus. Ο έλεγχος αντικατοπτρίζει την κατάσταση του οχήματος μόνο κατά την ημερομηνία και ώρα της επιθεώρησης. Όλες οι παρατηρήσεις και τα ευρήματα βασίζονται σε οπτικό και λειτουργικό έλεγχο, χωρίς αποσυναρμολόγηση εξαρτημάτων, εκτός εάν αναφέρεται διαφορετικά.

Παρά τη μέγιστη δυνατή προσοχή για την ακρίβεια των πληροφοριών, η Car Addicts Cyprus και ο τεχνικός που διενήργησε τον έλεγχο δεν φέρουν καμία ευθύνη ή υποχρέωση για μηχανικά, ηλεκτρικά ή αισθητικά προβλήματα που ενδέχεται να προκύψουν μετά την ημερομηνία του ελέγχου. Η παρούσα έκθεση δεν αποτελεί εγγύηση, διαβεβαίωση ή αποτίμηση της αξίας του οχήματος και δεν πρέπει να χρησιμοποιείται ως ο μοναδικός παράγοντας για λήψη απόφασης αγοράς.

09/2020- Toyota Vehicle Diagnostic Report

Vehicle Information

09/2020-/Toyota/Yaris/M15A-FKS
VIN: MXPA12-0002507

Odometer Reading: 31215 km
License Plate: --

Customer Information

Name: --

Tel: --

Device information

Scanner: MaxiSys Ultra
Version: V7.20

Serial Number: V1DGM4V01135
Repair Order Number:
V1DGM4V0113520260122122616660

System Scanned (32)

System		Status/DTC
Engine		✓ 0
Transmission		✓ 0
SRS airbag		✓ 0
Combination meter		✓ 0
Brake/EPB		✓ 0
Main body		✓ 0
Driver door motor		✓ 0
Rain and/or humidity sensor		✓ 0
Passenger door motor		✓ 0
Front recognition camera (Front lighting control)	ADAS	✓ 0
Entry and start		✓ 0
Power source control		✓ 0
Navigation system		✗ 1
Telematics		✓ 0
Front radar sensor	ADAS	✓ 0
Blind spot monitor (BSM) B	ADAS	✗ 1
Blind spot monitor (BSM) A	ADAS	✓ 0
Power integration No.1		✓ 0
Power distribution box		✓ 0
Clearance warning		✓ 0

Road sign assist	ADAS	✓ 0
Head-Up display	ADAS	✓ 0
Master switch		✓ 0
Central gateway		✓ 0
Pre-Collision system	ADAS	✓ 0
Rear camera	ADAS	✓ 0
Steering angle sensor (SAS)		✓ 0
Lane control	ADAS	✓ 0
Front recognition camera	ADAS	✓ 0
EMPS		✗ 1
Radar cruise 2	ADAS	✓ 0
Radar cruise 1	ADAS	✓ 0

DTC (3)

Navigation system (1 DTC)

DTC	Description	Status
B15A0	Lane master fault	History

Blind spot monitor (BSM) B (1 DTC)

DTC	Description	Status
C1AC100	Rear side radar sensor (module B) beam axis misalignment (horizontal)	Confirmed

EMPS (1 DTC)

DTC	Description	Status
U023A87	Lost communication with image processing module A missing message	Confirmed

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

車両引取先「兵庫県」 車両に関するお問合せ JU岐阜 058 398 5102
 送問合せ US物流 058-307-1066 (AS・Aucは毎月10日正午以降にJU岐阜から搬出。商談・後日着札は別対応)

[1945] 山
 90170
 お店のクルマ
 (店頭映像出品)

年式 3/4	車名・グレード GRヤリス RS	ドア 3 形状 HB
2WD・4WD 2WD	排気量 1500	型式 5BA-MXPA12

詳細点 4
内装 B

車歴 日産・()	
車検 年 月	
走行 2万 8千 3百 9 (km)	
色 アカ	カラー版 305
保証書 有・無	

シフト AT
市販 AC
車別 G

乗車定員 4名
積載量 kg
総重量 kg
名義期間 月 日

セールスポイント
 ・バドルソフト
 ・バックカウ

装備品	S/R	ABS	エア	エア	エア	ABS
	有	有	有	有	有	有
	有	有	有	有	有	有

リサイクル料 8530円 預託済

【出品店申告欄(不具合所・欠品・注意事項等)】

【検査員記入】

フルミ A
ル フラビング
名 A U

FW	キズ	ビキ	割レキ	シート	コゲ	穴	汚レ	シミ	錆レ	変レ
----	----	----	-----	-----	----	---	----	----	----	----

登録地	
車台地	MXPA12-0002507

車庫証明用	有・無	工 具	有・無	ジャッキ	有・無
-------	-----	-----	-----	------	-----

