



Larmos Autoservices

Technician: Andreas Larmou

Date: 22/01/2026

Customer Name: Car Addicts Cyprus


Yr/Make/Model: 2005 Mitsubishi Evo IX

VIN: N/A

Mileage: 111819kms

ENGINE & COOLING SYSTEM

Oil & coolant levels and condition



Engine noise / vibration / leaks

Cooling system hoses / radiator / fan


Belts & pulleys condition

ECU codes / exhaust smoke / idle quality

Comments: Ok

ELECTRICAL SYSTEM

Battery voltage / terminals / charging



Starter motor / alternator function

Lights & indicators / dashboard warnings

Comments: Needs new battery

AIR CONDITIONING & HVAC

Compressor / airflow / temperature



Heater function

Comments: Ok

DIAGNOSTIC SCAN

Fault codes retrieved



Systems check

Comments: No Faults

EXHAUST SYSTEM

Visual condition / corrosion



Mouting brackets secure

Comments: Ok

SUSPENSION & STEERING

Front & rear suspension bushes	✓		
Ball joints / tie rods / rack condition	✓		
Shock absorbers / struts / bushes	✓		

Comments: Ok

BRAKING SYSTEM

Brake pad / disc condition	✓		
Brake hoses / lines / leaks	✓		
Brake fluid level & color	✓		
Handbrake / ABS operation	✓		

Comments: Ok

TRANSMISSION, CLUTCH & DIFFERENTIAL

Gearshift operation / smoothness	✓		
Clutch pedal feel & bite point	✓		
Transmission fluid level / leaks	✓		
Differential operation / noises	✓		

Comments: Ok

WHEELS & TYRES

Tyre tread depth / brand matching			✓
Wear pattern	✓		
Wheel condition / cracks	✓		

Comments: Flat Spotted Tyres - Need Replacement asap

Mechanic's Signature: 

Date: _____

Disclaimer:

This Vehicle Inspection Report was produced for and paid for by Car Addicts Cyprus. The inspection reflects the vehicle's condition only at the time and date it was examined. All observations and findings are based on a visual and functional inspection carried out without dismantling any components, unless otherwise stated. While every effort has been made to ensure accuracy, Car Addicts Cyprus and the inspecting technician assume no responsibility or liability for any mechanical, electrical, or cosmetic issues that may arise after the date of inspection. This report does not constitute a warranty, guarantee, or valuation of the vehicle, and it should not be relied upon as the sole basis for a purchase decision.

Δήλωση Αποποίησης Ευθύνης:

Η παρούσα Έκθεση Ελέγχου Οχήματος εκπονήθηκε για λογαριασμό και με δαπάνη της Car Addicts Cyprus. Ο έλεγχος αντικατοπτρίζει την κατάσταση του οχήματος μόνο κατά την ημερομηνία και ώρα της επιθεώρησης. Όλες οι παρατηρήσεις και τα ευρήματα βασίζονται σε οπτικό και λειτουργικό έλεγχο, χωρίς αποσυναρμολόγηση εξαρτημάτων, εκτός εάν αναφέρεται διαφορετικά.

Παρά τη μέγιστη δυνατή προσοχή για την ακρίβεια των πληροφοριών, η Car Addicts Cyprus και ο τεχνικός που διενήργησε τον έλεγχο δεν φέρουν καμία ευθύνη ή υποχρέωση για μηχανικά, ηλεκτρικά ή αισθητικά προβλήματα που ενδέχεται να προκύψουν μετά την ημερομηνία του ελέγχου. Η παρούσα έκθεση δεν αποτελεί εγγύηση, διαβεβαίωση ή αποτίμηση της αξίας του οχήματος και δεν πρέπει να χρησιμοποιείται ως ο μοναδικός παράγοντας για λήψη απόφασης αγοράς.