



Larmos Autoservices

Technician: Andreas Larmou

Date: 22/01/2026

Customer Name: Car Addicts Cyprus


Yr/Make/Model: 2018 Mercedes-Benz GLA45 AMG

VIN: WDC1569522J586214

Mileage: 79350kms

ENGINE & COOLING SYSTEM

Oil & coolant levels and condition



Engine noise / vibration / leaks

Cooling system hoses / radiator / fan

Belts & pulleys condition


ECU codes / exhaust smoke / idle quality

Comments: Ok

Diagnostic Report Attached

ELECTRICAL SYSTEM

Battery voltage / terminals / charging



Starter motor / alternator function

Lights & indicators / dashboard warnings

Comments: Ok

AIR CONDITIONING & HVAC

Compressor / airflow / temperature



Heater function

Comments: Ok

DIAGNOSTIC SCAN

Fault codes retrieved



Systems check

Comments: Diagnostic Report Attached

EXHAUST SYSTEM

Visual condition / corrosion



Mouting brackets secure

Comments: No corrosion - All good

SUSPENSION & STEERING

Front & rear suspension bushes	✓		
Ball joints / tie rods / rack condition	✓		
Shock absorbers / struts / bushes	✓		

Comments: Ok

BRAKING SYSTEM

Brake pad / disc condition	✓		
Brake hoses / lines / leaks	✓		
Brake fluid level & color	✓		
Handbrake / ABS operation	✓		

Comments: Ok!

TRANSMISSION, CLUTCH & DIFFERENTIAL

Gearshift operation / smoothness	✓		
Clutch pedal feel & bite point	✓		
Transmission fluid level / leaks	✓		
Differential operation / noises	✓		

Comments: Ok

WHEELS & TYRES

Tyre tread depth / brand matching		✓	
Wear pattern	✓		
Wheel condition / cracks	✓		

Comments: Michelin Pilot Sport 4S

Rear Tyres will need replacement soon.

Mechanic's Signature: 

Date: 22.01.2026

Disclaimer:

This Vehicle Inspection Report was produced for and paid for by Car Addicts Cyprus. The inspection reflects the vehicle's condition only at the time and date it was examined. All observations and findings are based on a visual and functional inspection carried out without dismantling any components, unless otherwise stated. While every effort has been made to ensure accuracy, Car Addicts Cyprus and the inspecting technician assume no responsibility or liability for any mechanical, electrical, or cosmetic issues that may arise after the date of inspection. This report does not constitute a warranty, guarantee, or valuation of the vehicle, and it should not be relied upon as the sole basis for a purchase decision.

Δήλωση Αποποίησης Ευθύνης:

Η παρούσα Έκθεση Ελέγχου Οχήματος εκπονήθηκε για λογαριασμό και με δαπάνη της Car Addicts Cyprus. Ο έλεγχος αντικατοπτρίζει την κατάσταση του οχήματος μόνο κατά την ημερομηνία και ώρα της επιθεώρησης. Όλες οι παρατηρήσεις και τα ευρήματα βασίζονται σε οπτικό και λειτουργικό έλεγχο, χωρίς αποσυναρμολόγηση εξαρτημάτων, εκτός εάν αναφέρεται διαφορετικά.

Παρά τη μέγιστη δυνατή προσοχή για την ακρίβεια των πληροφοριών, η Car Addicts Cyprus και ο τεχνικός που διενήργησε τον έλεγχο δεν φέρουν καμία ευθύνη ή υποχρέωση για μηχανικά, ηλεκτρικά ή αισθητικά προβλήματα που ενδέχεται να προκύψουν μετά την ημερομηνία του ελέγχου. Η παρούσα έκθεση δεν αποτελεί εγγύηση, διαβεβαίωση ή αποτίμηση της αξίας του οχήματος και δεν πρέπει να χρησιμοποιείται ως ο μοναδικός παράγοντας για λήψη απόφασης αγοράς.

Benz Vehicle Diagnostic Report

Vehicle Information

--/Benz/GLA (156)/
VIN: WDC1569522J586214

Odometer Reading: 79304 km
License Plate: --

Customer Information

Name: --

Tel: --

Device information

Scanner: MaxiSys Ultra
Version: V6.25

Serial Number: V1DGM4V01135
Repair Order Number:
V1DGM4V0113520260122115422331

System Scanned (46)

System	Status/DTC
ECM(Engine Control Unit)	0
TCM(Transmission Control Unit)	0
ESP(Electronically controlled vehicle stability braking system control unit)	0
SRS(Supplemental Restraint System Control Unit)	0
LIN:WSS-1(Weight Sensing Sensor Control Unit)	0
KI(Instrument Cluster)	0
EPB(Electric Parking Brake)	0
TPM(Tire Pressure Monitor Control Unit)	0
PTS(Parking System)	0
SAM(Signal Acquisition Control Unit)	1
LIN:AISP(Interior mirror)	0
LIN:BSN(Battery Sensor)	0
LIN:DBE-1(Sunroof Control Unit)	0
LIN:OBF(Upper Control Panel)	0
LIN:SHM(Seat Heating)	0
LIN:VCS-1(Light Sensor)	0
EZS(Electronic Ignition Lock Control Unit)	0
ES(Electric Power Steering)	0
KLA(Air Conditioner Control Unit)	1

AWD(Four Wheel Drive)		✓ 0
HU(Head Unit Control Unit)		✓ 0
DSI(Shift Lever Control Unit)		✓ 0
KG(Keyless Go Control Unit)		✓ 0
SW-SW-R(Right Headlamp Control Unit)	ADAS	✓ 0
SW-SW-L(Left Headlamp Control Unit)	ADAS	✓ 0
ABA(Collision Prevention Assist)	ADAS	✓ 0
DMFL(Left Front Door Control Unit)		✓ 0
LIN:DSM_MFL(Left Front Seat Adjustment Switch)		✓ 0
DMFR(Right Front Door Control Unit)		✓ 0
LIN:DSM_MFR(Right Front Seat Adjustment Switch)		✓ 0
ZBE(Head Unit Display)		✓ 0
SOUND(Sound System Amplifier Control Unit)		✗ 1
RFK-C(Reversing Camera)	ADAS	✓ 0
PSD(Sunroof Control Unit)		✓ 0
MRM(Steering Column Control Unit)		✓ 0
MFK(Multifunction Camera)	ADAS	✓ 0
KAB(Reversing Camera Cover Control Unit)	ADAS	✓ 0
HKS(Trunk Lid Control Unit)		✓ 0
FSCU(Fuel Pump Control Unit)		✓ 0
ESEP(Passenger Side Electric Seat Adjustment Control Unit)		✓ 0
ESED(Driver Side Electric Seat Adjustment Control Unit)		✓ 0
EDW(Interior Protection System Control Unit)		✓ 0
LIN:AS(Alarm Siren)		✓ 0
DTA(Telematics Service Control Unit)		✓ 0
DAB(Digital Audio)		✓ 0
AMGW(Amg Bus Gateway Control Unit)		✓ 0

 DTC (3)**SAM(Signal Acquisition Control Unit) (1 DTC)**

DTC	Description	Status
B21059A	The capacity of the starter battery is too low. The operating conditions for the component or the system are not satisfied.	Stored

KLA(Air Conditioner Control Unit) (1 DTC)

DTC	Description	Status
912749	The air quality sensor has a malfunction. There is an internal electrical fault.	Active and stored

SOUND(Sound System Amplifier Control Unit) (1 DTC)

DTC	Description	Status
B15E513	Speaker A on channel 7 has a malfunction. There is an open circuit.	Active and stored

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.