



Larmos Autoservices

Technician: Andreas Larmou

Date: 17/01/2026

Customer Name: Car Addicts Cyprus


Yr/Make/Model: 2010 BMW 320i Cabriolet

VIN: WBAWK72090P230280

Mileage: 149000kms

ENGINE & COOLING SYSTEM

Oil & coolant levels and condition



Engine noise / vibration / leaks

Cooling system hoses / radiator / fan


Belts & pulleys condition

ECU codes / exhaust smoke / idle quality

Comments: Ok

ELECTRICAL SYSTEM

Battery voltage / terminals / charging



Starter motor / alternator function

Lights & indicators / dashboard warnings

Comments: Daylight running lights - error

AIR CONDITIONING & HVAC

Compressor / airflow / temperature



Heater function

Comments: Ok

DIAGNOSTIC SCAN

Fault codes retrieved



Systems check

Comments: Fault Codes Attached

EXHAUST SYSTEM

Visual condition / corrosion



Mouting brackets secure

Comments: No corrosion - All good

SUSPENSION & STEERING

Front & rear suspension bushes	✓		
Ball joints / tie rods / rack condition	✓		
Shock absorbers / struts / bushes	✓		

Comments: Ok

BRAKING SYSTEM

Brake pad / disc condition	✓		
Brake hoses / lines / leaks	✓		
Brake fluid level & color	✓		
Handbrake / ABS operation	✓		

Comments: Ok

TRANSMISSION, CLUTCH & DIFFERENTIAL

Gearshift operation / smoothness	✓		
Clutch pedal feel & bite point	✓		
Transmission fluid level / leaks	✓		
Differential operation / noises	✓		

Comments: Ok

WHEELS & TYRES

Tyre tread depth / brand matching	✓		
Wear pattern	✓		
Wheel condition / cracks	✓		

Comments: Ok

Mechanic's Signature: 

Date: 17.01.2026

Disclaimer:
This Vehicle Inspection Report was produced for and paid for by Car Addicts Cyprus. The inspection reflects the vehicle's condition only at the time and date it was examined. All observations and findings are based on a visual and functional inspection carried out without dismantling any components, unless otherwise stated. While every effort has been made to ensure accuracy, Car Addicts Cyprus and the inspecting technician assume no responsibility or liability for any mechanical, electrical, or cosmetic issues that may arise after the date of inspection. This report does not constitute a warranty, guarantee, or valuation of the vehicle, and it should not be relied upon as the sole basis for a purchase decision.

Δήλωση Αποποίησης Ευθύνης:
Η παρούσα Έκθεση Ελέγχου Οχήματος εκπονήθηκε για λογαριασμό και με δαπάνη της Car Addicts Cyprus. Ο έλεγχος αντικατοπτρίζει την κατάσταση του οχήματος μόνο κατά την ημερομηνία και ώρα της επιθεώρησης. Όλες οι παρατηρήσεις και τα ευρήματα βασίζονται σε οπτικό και λειτουργικό έλεγχο, χωρίς αποσυναρμολόγηση εξαρτημάτων, εκτός εάν αναφέρεται διαφορετικά.

Παρά τη μέγιστη δυνατή προσοχή για την ακρίβεια των πληροφοριών, η Car Addicts Cyprus και ο τεχνικός που διενήργησε τον έλεγχο δεν φέρουν καμία ευθύνη ή υποχρέωση για μηχανικά, ηλεκτρικά ή αισθητικά προβλήματα που ενδέχεται να προκύψουν μετά την ημερομηνία του ελέγχου. Η παρούσα έκθεση δεν αποτελεί εγγύηση, διαβεβαίωση ή αποτίμηση της αξίας του οχήματος και δεν πρέπει να χρησιμοποιείται ως ο μοναδικός παράγοντας για λήψη απόφασης αγοράς.

2008_01 BMW Vehicle Diagnostic Report

Vehicle Information

 2008_01/BMW/3'/320i_N43/N43
 VIN: WBAWK72090P230280

 Odometer Reading: 149104 km
 License Plate: --

Customer Information

Name: --

Tel: --

Device information

 Scanner: MaxiSys Ultra
 Version: V18.02

 Serial Number: V1DGM4V01135
 Repair Order Number:
 V1DGM4V0113520260117091250905

System Scanned (20)

System	Status/DTC
DME (Engine-Digital Motor Electronics)	7
EGS (Electronic Transmission Management)	0
DSC (Dynamic Stability Control)	0
ACSM (Airbag-Advanced Crash Safety Module)	0
KOMBI (Instrument Cluster)	0
CAS (Car Access System)	0
MOST (Media Oriented Systems Transport System Analysis)	0
JBE (Junction Box Electronics)	0
EKPS (Electric Fuel Pump Control)	0
CTM (Convertible Top Module)	0
EPS (Electric Power Steering)	0
FZD (Roof Function Center)	0
CCC-GW (Car Communication Computer-Gateway)	1
CIC (Car Information Computer)	1
PDC (Park Distance Control)	0
SMFA (Driver Seat Module)	0
SMBF (Front Passenger Seat Module)	0
FRM (Footwell Module)	2
IHKA (Integrated Automatic Heating And A/C System)	0

RLS (Rain/Light Sensor)

1

 DTC (12)

DME (Engine-Digital Motor Electronics) (7 DTCs)

DTC	Description	Status
002ED3	Digital Motor Electronics (DME), generator, type incorrect	present
002AF4	Digital Motor Electronics (DME), NOx sensor, electric	Absent
002AF2	Digital Motor Electronics (DME), NOx sensor, lambda linear	Absent
002AF6	Digital Motor Electronics (DME), NOx sensor, lambda binary	Absent
0030DA	Digital Motor Electronics (DME), NOx sensor signal	Absent
002C31	Oxygen Sensor Emissions Control	Absent
002C6C	Digital Motor Electronics (DME), mixture control to catalytic converter, system check	Absent

CCC-GW (Car Communication Computer-Gateway) (1 DTC)

DTC	Description	Status
S 0376	Communication not possible with media oriented systems transport gateway	Permanent

CIC (Car Information Computer) (1 DTC)

DTC	Description	Status
S 0375	Communication not possible with headunit	Permanent

FRM (Footwell Module) (2 DTCs)

DTC	Description	Status
00A8AF	FRM: Fog light, right, faulty, E90 M3: daytime running light, right, faulty	present
00A8AE	FRM: Fog light, left, faulty, E90 M3: daytime running light, left, faulty	present

RLS (Rain/Light Sensor) (1 DTC)

DTC	Description	Status
S 0166	Communication not possible with rain/light solar sensor	Permanent

Technician Notes