



**Larmos Autoservices**

Technician: Andreas Larmou

Date: 27/04/2026

Customer Name: Car Addicts Cyprus


Yr/Make/Model: 2023 Mazda CX30

VIN: DMEJ3P-106521


Mileage: 17,300km

### ENGINE & COOLING SYSTEM

Oil & coolant levels and condition



Engine noise / vibration / leaks



Cooling system hoses / radiator / fan



Belts & pulleys condition




ECU codes / exhaust smoke / idle quality



Comments: All Good

### ELECTRICAL SYSTEM

Battery voltage / terminals / charging



Starter motor / alternator function



Lights & indicators / dashboard warnings



Comments: All Good

### AIR CONDITIONING & HVAC

Compressor / airflow / temperature



Heater function



Comments: All Good

### DIAGNOSTIC SCAN

Fault codes retrieved



Systems check



Comments: No Codes

### EXHAUST SYSTEM

Visual condition / corrosion



Mouting brackets secure



Comments: All Good

SUSPENSION & STEERING

|                                         |                                    |                                   |                                   |
|-----------------------------------------|------------------------------------|-----------------------------------|-----------------------------------|
| Front & rear suspension bushes          | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Ball joints / tie rods / rack condition | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Shock absorbers / struts / bushes       | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |

Comments: All Good

BRAKING SYSTEM

|                             |                                    |                                   |                                   |
|-----------------------------|------------------------------------|-----------------------------------|-----------------------------------|
| Brake pad / disc condition  | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Brake hoses / lines / leaks | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Brake fluid level & color   | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Handbrake / ABS operation   | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |

Comments: All Good

TRANSMISSION, CLUTCH & DIFFERENTIAL

|                                  |                                    |                                   |                                   |
|----------------------------------|------------------------------------|-----------------------------------|-----------------------------------|
| Gearshift operation / smoothness | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Clutch pedal feel & bite point   | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Transmission fluid level / leaks | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Differential operation / noises  | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |


Comments: Gear selector knob is loose

WHEELS & TYRES

|                                   |                                    |                                   |                                   |
|-----------------------------------|------------------------------------|-----------------------------------|-----------------------------------|
| Tyre tread depth / brand matching | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Wear pattern                      | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |
| Wheel condition / cracks          | <div><div><div>✓</div></div></div> | <div><div><div></div></div></div> | <div><div><div></div></div></div> |

Comments: Factory Fitted Bridgestone Turanza 215/55/R18 (Prod. 07/2023)

Tread depth ok

Mechanic's Signature: 

Date: 27/04/2026

**Disclaimer:**  
This Vehicle Inspection Report was produced for and paid for by Car Addicts Cyprus. The inspection reflects the vehicle's condition only at the time and date it was examined. All observations and findings are based on a visual and functional inspection carried out without dismantling any components, unless otherwise stated. While every effort has been made to ensure accuracy, Car Addicts Cyprus and the inspecting technician assume no responsibility or liability for any mechanical, electrical, or cosmetic issues that may arise after the date of inspection. This report does not constitute a warranty, guarantee, or valuation of the vehicle, and it should not be relied upon as the sole basis for a purchase decision.

**Δήλωση Αποποίησης Ευθύνης:**  
Η παρούσα Έκθεση Ελέγχου Οχήματος εκπονήθηκε για λογαριασμό και με δαπάνη της Car Addicts Cyprus. Ο έλεγχος αντικατοπτρίζει την κατάσταση του οχήματος μόνο κατά την ημερομηνία και ώρα της επιθεώρησης. Όλες οι παρατηρήσεις και τα ευρήματα βασίζονται σε οπτικό και λειτουργικό έλεγχο, χωρίς αποσυναρμολόγηση εξαρτημάτων, εκτός εάν αναφέρεται διαφορετικά.

Παρά τη μέγιστη δυνατή προσοχή για την ακρίβεια των πληροφοριών, η Car Addicts Cyprus και ο τεχνικός που διενήργησε τον έλεγχο δεν φέρουν καμία ευθύνη ή υποχρέωση για μηχανικά, ηλεκτρικά ή αισθητικά προβλήματα που ενδέχεται να προκύψουν μετά την ημερομηνία του ελέγχου. Η παρούσα έκθεση δεν αποτελεί εγγύηση, διαβεβαίωση ή αποτίμηση της αξίας του οχήματος και δεν πρέπει να χρησιμοποιείται ως ο μοναδικός παράγοντας για λήψη απόφασης αγοράς.